## FIELD INSPECTION REPORT

GTSNY

	Inspection:	30/12/2020	District: lastne	<del></del>
Division: Danebux			Length (km): 1: 0	
	fthe Read:	musy Ro		aind toli
	Programme:	MAINTENANCE		
Package			Road Id No.:	
			Under Maintenance	
	a case of:	New Connectivity/U	p gradation/ Maintenance	. ,
SI. No.		Parameters to l	oe checked	Remarks
	Pavement			YEAR THE LAND
a)	Road Junction condition			SAG
b)	Condition of Sur	rfacing		SÆ
c)	Riding Quality			SAU
	Road Camber			SÆ
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
1)	Contraction Joints provided or not (CC Pavement)			Yes/No
	Compaction of flank/slope & raincuts if any			Yes/No
2. (	Cross Drainage		ENT AT THE	77 - F8
a) (	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b) C	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
) C	Condition of railings/slab/approach for Bridges			S/SRI/U
R	oad Furniture	24		
) W	hether sign bo ones/Pavement re	ards/informatory/cau oad markings are pro	ntionary Board/km & 200m ovided and maintained	Yes/No
Co	mpliance Histo	n i		
Sta	tus of ATR's &	any others		and the second

**Overall Rating** 

Satisfactory but requires Improvement (SRI)	0
	<u>ڪ_</u>
Unsatisfactory (U)	· · · ·

30/12/2020 30/1 J.E Bilda.

(Signature)

NAME:

DESIGNATION: