

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Name of work → NH-80					
Se Atakai batte me biser					
Marammati karya.					
② Agency →					
③ Agreement →					
④ Date of entry. 16/12/2019					

work done

① Granular sub base with
well graded material
Gable 4 mm.

$$10 \times 2.10 \times 1.20 \times 0.15 = 3.78 \text{ m}^3$$

$$8 \times 2.10 \times 1.40 \times 0.15 = 3.36 \text{ m}^3$$

$$8 \times 1.80 \times 1.80 \times 0.15 = 3.84 \text{ m}^3$$

$$10 \times 2.20 \times 1.60 \times 0.15 = 5.28 \text{ m}^3$$

$$1.60 \times 1.10 \times 1.40 \times 0.15 = 1.12 \text{ m}^3$$


$$\text{Total } 16.71 \text{ m}^3$$


② Sublayer of brick bats as per technical
specification etc.

Sch. XLV-Form No. 134

2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(20.00 * 12.00 + 10.00) * 3.75 X					
20.00 * 3.75 X 0.60 = 45.00 m ³					
12.00 * 3.75 X 0.45 = 20.25 m ³					
10.00 * 3.75 X 0.45 = 16.88 m ³					
					82.13 m ²
Material statement					
X					
Stone metal → 12.52 m ³					
Sand → 8.35 m ³					
Brick bats → 82.13 m ³					
↑					


 16-12-19
 36
 2


 Neem
 17-12-19

Abstract of cost

X
3

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Granular sub base with well graded material.					
at ridge - ①	16.31 m ²				
at ridge - ②	1746.91 m ²				28492.00
② supplying & laying brick bds as per technical - do -					
at ridge - ①	82.13 m ²				
at ridge - ②	1528.89 m ²				12532.00
Wsg 10x C.P					153813.00
					53812.00

Rs. 158432.00

P.S.
16/12/19
B.E.

M.T.
17-12-19
P.T.

अधीक्षण अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य अंचल, मुंगेर।

संयुक्त स्थल निरीक्षण प्रतिवेदन

आज दिनांक 06.03.2020 को अधीक्षण अभियंता, ग्रामीण कार्य विभाग, कार्य अंचल, मुंगेर एवं कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मुंगेर द्वारा FDR अन्तर्गत NH-80 ईटहरी भाया चमनगढ़ कार्य का संयुक्त स्थल निरीक्षण किया गया, जो प्राक्कलन के अनुरूप पाया गया एवं संतोषप्रद है।

अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुंगेर।

ज्ञापांक :- 397

मुंगेर दिनांक :- 06/03/2020

प्रतिलिपि :- कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मुंगेर को सूचनार्थ एवं आवश्यक कार्रवाई हेतु प्रेषित।

अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुंगेर।