

Record measurement

Name to work—
 Location of work—
 Agency by which work is executed—
 Date of measurement—
 Date and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Kanti Bazar Bazar					
To Pabwelpur Road under					
FDR at Block Hills					
Agency:					
Authority:					
Item 1 Providing & Laying dry					
graded frame Khod or					
stone filter under brick					
pitching / brick bats or					
Boulder pitching in 1:1 pe					
or cpm including light					
ramming etc all complete					
as per approved design					
specification & dimensions of 1:2					
1st KM - 1x 18.0 x 4.50 + 4.60 + 4.90 +					
10.20 + 10.60 + 11.0					
6					
1.90 + 2.20 + 2.60					
= 298.98					m ³
2nd KM					
1x 15.0 x 2.0 + 2.10 + 2.30 + 3.0 +					
8.50 + 3.0					
6					
2.50 + 3.0					
= 218.63					m ³
2					
Total Qty 517.61 m ³					

19/11/2019
 JE

Continuation

19/11/2019
 AE

Scanned by CamScanner

Scanned by CamScanner

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D.	
ABSTRACT OF COST					
Item ①	Paving & laying				
	dry graded theme then				
	or stone filler under				
	brick paviors / brick bats				
	or boulder paviors or				
	cotton including rights				
	materials etc. all complete				
	JOS as per approved				
	design & specification &				
	direction of E/I				
	Qty 5.17 6.10 ² m ² m ² m ²				
	5.17 6.10 ² m ² m ² m ²				
	5.17 6.10 ² m ² m ² m ²				

[illegible]

Continuation

Date: - 27.12.2019

1. Name of PIUs - Er. Ramashwar Singh.
2. Name of Block/Road - Hilsa/Hilsa - Revibansbigha to Patwardpur.

A. For Road

1. Damage Location/Chainage :- 1st km
2. Damage Length :- 33.0 M
3. Nature of Damage :- Breach
4. Details of Restoration Works :-
 - i. Material being used in Restoration works :- Brick bats
 - ii. Equipments/Tools being used in Restoration works :- Tractor, J.C.B & Roller.
 - iii. Procedure taken up in Restoration works :- Filling brick bats in Breach and Rolling the same.
 - iv. Restored Length :- 33.0 M


B. For Bridge

1. Damage Location/Chainage :- N/A
2. Damage Length :- N/A
3. Nature of Damage :- N/A
4. Details of Restoration Works :- N/A
 - i. Material being used in Restoration works :- N/A
 - ii. Equipments/Tools being used in Restoration works: N/A
 - iii. Procedure taken up in Restoration works :- N/A
 - iv. Restored Length :- N/A

C. Requirement of new CD/Bridge

- i. Name of Road :-
- ii. Location/Chainage :-
- iii. Type of CD work/Length required :-

- Upload one Photograph of damaged portion if available
- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode.


Signature of JE/AE/EE


JE


29/12/19
AS


Signature

(Name of Inspector)