

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF WORK - IMPROVEMENT					
OF REPAIR CHOCK TO					
BEEN IN MAINTENANCE					
ROAD P. H. 620 - M. H.					
N/19 - 20 M. H. 620					
W. 2/13					
N/19 - 20 CONSTRUCTION					
& DEVELOPMENT PUT,					
UTILE, P. H. 620					
AG. 20 - 131 M. H. D/2019-20					
DATE OF WORK - 28/11/2012					
DATE OF COMPLETION - 22/12/2012					
DATE OF COST - 17/5/2013					
ABSTRACT OF COST					
(1/54) CLOSING & GRADING					
20 sq. ft. area					
W. 20 - (54) & C. 100 - (1)					
C. 100 = 0.390 H. 620					
C. 100 49496.70 - P. 19,304 =					
(2/55) CONSTRUCTION SUBSIDY					
& other work 100 sq. ft.					
W. 20 - (55) & C. 100 - (2)					
C. 100 = 816.75 H. 620					
C. 100 126.75 - P. 1,43,300 =					
C. 100 1,62,604 =					

Continuation

[illegible]