

Continuation C.O. 56.24

Sch. XLV-Form No. 134

16

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B. E	6457021
Item 11/ Poor quality of Packlet					
vide item no. ③ work ①/12					
Qty = 3003.75 m ² @ 13.92				1412	41812
Item 12/ Poor quality of Pucc					
vide item no. ③ work ①/13					
Qty = 3003.75 m ² @ 203.17				1412	610272
Item 13/ Poor quality of concrete					
- Plastic Paint					
Qty = 313.90 m ² @ 735.40				1412	230477
					733652
(-) 10% Below					(-) 733652
1 Total					6602924
Add 12% GST					880390
Subtotal 12% L.C.					73366
Total					8290538
(-) 10% Below					(-) 829054
Total					7461304
(-) 10% Below					(-) 219731
Total					5266762

Continuation

C/S
 24.11.20
 Executive Engineer
 R.W.D. Works Division
 Muzaffarpur East-I