

प्रमाणित किया जाता है कि इस मापी -  
पुस्त में मशीन द्वारा अंकित कुल  
100 (एक सौ) पन्ने हैं, जिमें M.M.G.  
S.Y. (SC) मद अन्तर्गत सेवरा दुर्गा-  
वती गाँव से देवरा पत्र का सापी  
लेने हेतु श्री रामचन्द्र पंडित, सहा.  
आम्र कार्य अवट प्रमंडल कुदरा के  
नाम पर निर्गत किया जाता है)

कार्यपालक अभियंता  
मानीय कार्य विभाग  
कार्य प्रमंडल, सोलविया  
15/5/20

Reimbursement  
15/5/20

M.M.G.S.Y. SC  
Sch. XLV—Form No. 134

कार्य अवट प्रमंडल कुदरा DIVISION  
श्री रामचन्द्र पंडित, सहा. आम्र SUBDIVISION  
पत्र - सेवरा दुर्गावती गाँव से देवरा पत्र  
संवेदक - जय बजरंग अन्तरा  
एकपत्रनामा - 135BD/11.5.20

**Measurement Book**

No. 418  
20-21

Name of Officer \_\_\_\_\_

Date of first entry \_\_\_\_\_

Date of last entry \_\_\_\_\_

1  
 Name of work—  
 Situation of work—  
 Agency by which work is executed—  
 Date of measurement—  
 No. and date of agreement.  
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

| Particulars                             | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------------------|-------------------------------|----|----|----|------------------|
|                                         | No.                           | L. | B. | D. |                  |
| 1st and on A/C Bill                     |                               |    |    |    |                  |
| ett - 14 mgsy                           |                               |    |    |    |                  |
| M/W! Construction of Road               |                               |    |    |    |                  |
| from <sup>New 59</sup> Durgawati Branch |                               |    |    |    |                  |
| To Dewa Path.                           |                               |    |    |    |                  |
| Agency! - M/S Tai Bajrang               |                               |    |    |    |                  |
| Construction.                           |                               |    |    |    |                  |
| Date of start 11/5/20                   |                               |    |    |    |                  |

|                                              |  |  |  |  |
|----------------------------------------------|--|--|--|--|
| Date of Completion 10/5/21                   |  |  |  |  |
| Date of Actual Completion! work in Progress. |  |  |  |  |

|                                             |  |  |  |  |
|---------------------------------------------|--|--|--|--|
| ① clearing and grubbing                     |  |  |  |  |
| Road land do                                |  |  |  |  |
| all completely                              |  |  |  |  |
| $10 \times 30.00 \times 3.50 = 1050.00 m^2$ |  |  |  |  |
| $10 \times 30.00 \times 3.50 = 1050.00 m^2$ |  |  |  |  |
| $10 \times 30.00 \times 3.50 = 1050.00$     |  |  |  |  |
| $10 \times 30.00 \times 3.50 = 1050.00$     |  |  |  |  |
| $5 \times 30.00 \times 3.50 = 525.00$       |  |  |  |  |

Continuation

4725.00  
 = 0.4725 Hect

Sch: XV—Form No. 134

| Particulars                          | Details of actual measurement |    |    |    | Contents of area |
|--------------------------------------|-------------------------------|----|----|----|------------------|
|                                      | No.                           | L. | B. | D. |                  |
| 2.96 m <sup>3</sup> city vide P (15) |                               |    |    |    |                  |
| Qs 5700 = 65/100 m 16873 =           |                               |    |    |    |                  |
| (18/25) Por Boroumasonry             |                               |    |    |    |                  |
| work in cm (1.4)                     |                               |    |    |    |                  |
| in head wall                         |                               |    |    |    |                  |
| 30.606 m <sup>2</sup> city vide (16) |                               |    |    |    |                  |
| Qs 6362 = 22/100 194127 =            |                               |    |    |    |                  |
| (13/26) Por. and Laying              |                               |    |    |    |                  |
| R-e-e Repairs                        |                               |    |    |    |                  |
| for culvert on                       |                               |    |    |    |                  |
| 1st class bedding                    |                               |    |    |    |                  |
| of P.C.C. masonry                    |                               |    |    |    |                  |
| Single Row                           |                               |    |    |    |                  |
| 7.50 m city vide (16)                |                               |    |    |    |                  |
| Qs 3549 = 44/100 26621 =             |                               |    |    |    |                  |
| (14/27) plastering work              |                               |    |    |    |                  |
| Cement-Mortar                        |                               |    |    |    |                  |
| (1.4) on brickwork                   |                               |    |    |    |                  |
| in Sub. structure                    |                               |    |    |    |                  |
| as per Tech spec                     |                               |    |    |    |                  |
| 66.85 m <sup>2</sup> city vide (16)  |                               |    |    |    |                  |
| Qs 330.74 m <sup>2</sup> to 22/23 =  |                               |    |    |    |                  |

Continuation

N 6222.707 =

$$\begin{array}{r}
 15602427 \\
 \text{less Prepaid Divd} \\
 \text{Bill Value} \\
 \text{Wdp } (17) \text{ } 4048115 = \\
 1554322 =
 \end{array}$$

$$\begin{array}{r}
 25/9/20 \\
 25/9/20 \\
 \text{AL}
 \end{array}$$

$$\begin{array}{r}
 13/1/20
 \end{array}$$

Scanned with CamScanner