

MMBSY (SC)

1

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement -

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work: - (Consider					
Machya Nityala Pokasiya					
To Tansi Talu Hoker					
Telolita Machya					
Nityala Hote Nur					
Telolita Sam Sam Hote					
ke Hote Hote.					
Head: - MMBSY (SC)					
Agreement: - 30830 of 2018-19					

Agency: - B. G. J. P. P. P.
 In the field of development
 Pvt. Ltd. At: G. K. H. H. H.
 Near Shilpa Mahalir.

Date of start: - 20/06/2018

Date of comp: - 29/06/2019

Record of work

R. C. C. Box culvert 20x20

Item (1) Box culvert in excavation

for foundation - 1.0 - 1.0

complete 1.0

Box culvert

$$1 \times 6 \times 3.50 \times 0.650 = 13.65 \text{ m}^3$$

$$\text{Cut off wall } 2 \times 3.50 \times 1.30 \times 1.80 = 16.38 \text{ m}^3$$

C.O.

$$30.03 \text{ m}^3$$

Continuation

Continuation

Scanned with CamScanner