

Name of work -
 Situation of work -
 Agency by which work is executed
 Date of measurement
 No. and date of agreement
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of the work:- Restoration of traffic from Bhanuamipuz Rajdhani to B Kothi Block Bander via Sahid Gangi					
Charge head- 2245					
Authority - RWD letter no- 2789 dated 21/08/2020 and verbal order of EE RWD Mandaha Agency:-					

Kothi
2 rias

Sand bag

Date of Entry - 20/11/2020
 RECORD ENTRY

① Providing brick bats including
 Spreading laying Compacting -
 do - do - do - do -

2021

$$40m \times \left(\frac{4.68 + 6.60}{2} \right) \times \left(\frac{1.6 + 1.5}{2} + 2.40 + 2.90 + 1.20 \right) m$$

$$= 40m \times 5.64m \times 1.92m = 433.15 m^3$$

$$\text{Less for H.P} = 7.5 \times 3.14 \times \left(\frac{1.15}{2} \right)^2 = (-) 7.79 m^3$$

Wi

Continuation

$$\text{Total} = 422.96 m^3$$

Continuation

30.11.21

Particulars	Details of actual measurement				Contents of area
	No	L	B	H	
<u>ABSTRACT OF COST</u>					
① providing Brick bats including Spreading Laying Compacting do					
(vide-TMB-page-01)					
Qty = 422.96 m ³					
@ Rs 1717.37/m ³					Rs 726379=
② Labours for driving 62 mm to 75 mm dia bamboo piles do					
(vide-TMB-page-02)					
Qty = 893 m					
@ Rs 26.35/m					Rs 23,530=
③ Labours for filling Cement bag do					
(vide TMB page-02)					
Qty = 800 Bag					
@					
④ Supplying fittings and fixing of bamboo 62 mm to 75 mm do					
Qty = 536 mts					
@ Rs 4.59/m					Rs 2460=0

Continuation

3
Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	H	
<u>ABSTRACT OF COST</u>					
① providing Brick bats including spreading Laying Compacting					
do					
(vide-TMB-page-01)					
Qty = 422.96 m ³					
@ Rs 1717.37/m ³ Rs 726379 =					
② Labour for driving 62 mm to 75 mm dia bamboo piles					
do					
(vide-TMB-page-02)					
Qty = 893 m					
@ Rs 26.35/m Rs 23,530 = 0					
③ Labour for filling Cement bag					
do					
(vide TMB page-02)					
Qty = 800 Bag					
@					
④ Supplying fitting and fixing of bamboo 62 mm to 75 mm					
do					
Qty = 536 mts					
@ Rs 4.59/m Rs 2460 =					

Continuation

Inspection Report for flood damage work

Date:

1. Name of PIUs- Nandaha

2. Name of Block/Road- Bhawanipur / Bhawanipur Rajdham to B. Kothi Block
Border via Sahid gram

A. For Road

1. Damage Location/Chainage :
2. Damage Length : 40.0 M
3. Nature of Damage : wash out due to flood
4. Details of Restoration :
 - i Material being used in Restoration : Bamboo, Hume pipe, sand bags, crick bats
 - ii Equipment/Tools being used in Restoration works: Tractor
 - iii Procedure taken up in Restoration works : Manual
 - iv Restored Length : 40.0M

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
 - i Material being used in Restoration :
 - ii Equipment/Tools being used in Restoration works:
 - iii Procedure taken up in Restoration works :
 - iv Restored Length :

Signature of JE/AE/EE

Kumari
28/01/2021
JH

28/1/21
AG

EL-

Signature

(Name of Inspector)

28/1/2021