

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Executive Engineer,
Rural Works Department,
Works Division Dhamdaha (Pune)

Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

ABSTRACT OF COST

(1) providing brick bats including
spreading laying compacting
do do do do

(vide TMR-page-01)

Qty = 185.85 m³

@ Rs 1717.37/m³ Rs 319173 = 00

Total = 319173 = 00

Add 12% GST Rs 38300 = 00

Add 1% labour Cess Rs 3191 = 00

Add 10% S.F. Rs 19,700 = 00

Total = 3,80,364 = 00

sum
a/102/m
JPZ

Inspection Report for flood damage work

Date:

1. Name of PIUs- Khanda

2. Name of Block/Road- Barabara Kothi/Nathpur to Chahbacha

A. For Road

1. Damage Location/Chainage :
2. Damage Length : 8.0 M
3. Nature of Damage : Overlapping of Rain water the Road has been washed out
4. Details of Restoration :
 - i Material being used in Restoration : Brick bats
 - ii Equipment/Tools being used in Restoration works: Tractor
 - iii Procedure taken up in Restoration works : Manual
 - iv Restored Length : 8.0 M

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
 - i Material being used in Restoration :
 - ii Equipment/Tools being used in Restoration works:
 - iii Procedure taken up in Restoration works :
 - iv Restored Length :

Signature of JE/AE/EE

[Signature]
8/11/20
AE

28.01.21
EB

Signature

(Name of Inspector)

[Signature]
8/11/20

508

28/01/2021

T.E.