

Name of work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement -
 (These four lines should be repeated at the commencement of the measurements relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Restoration of					
Traffic from Maikhand Milk					
to Devi Road.					
Charge Road - 2245					
Authority - R.W.D. letter No. 2789					
dated 21/08/2020 and verbal					
order of E.E RWD Dhamdaha					
Agency:- Purua Construction					
Kanchan Maadhubini Purua					
Date of Entry:-					

① providing Brick bats including

Spreading, laying, compacting -

do do do

$$1 \times 5.0 \times \left(\frac{12.55 + 5.02}{2} \right) \times \left(\frac{1.90 + 2.90}{2} + 2.60 \right) = 46.68 \text{ m}^3$$

$$1 \times 4.8 \times \left(\frac{2.45 + 4.40}{2} \right) \times \left(\frac{1.55 + 2.50}{2} + 1.80 \right) = 32.06 \text{ m}^3$$

$$1 \times 3.9 \times \left(\frac{1.50 + 3.53}{2} \right) \times \left(\frac{1.60 + 2.60}{2} + 1.90 \right) = 19.94 \text{ m}^3$$

$$\text{Total} = 98.68 \text{ m}^3$$

1 cum/m³
 30/11/2020
 J12
 Executive Engineer,
 Rural Works Department
 Works Division Dhamdaha (Purua)

Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
<u>ABSTRACT</u>					
① providing Brick bats including spreading Laying Compacting					
— do — do —					
TMB - page - 01 =					98.68 m^3
@ $1717.37/\text{m}^3$ =					$1,69,470 = \infty$
Total =					$1,69,470 = \infty$
Add GST @ 12% =					$20,336 = \infty$
Add Labour cess @ 1% =					$1694 = \infty$
Total =					$1,91,500 = \infty$
Add signorag fee @ 10% =					$10,400 = \infty$
Total =					$2,01,900 = \infty$

cum. inv
 01/02/2021
 JES

Inspection Report for flood damage work

Date:

1. Name of PIUs- *Dhandaha*

2. Name of Block/Road- *Barbara Kothi/ Maikhand Nilik to Devi Road*

A. For Road

1. Damage Location/Chainage :

2. Damage Length : *13.7 M*

3. Nature of Damage : *Sideloape damage due to flood*

4. Details of Restoration :

i Material being used in Restoration : *brick bats*

ii Equipment/Tools being used in Restoration works: *Troctor*

iii Procedure taken up in Restoration works : *Manual*

iv Restored Length : *13.7 M*

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE/AE/EE

[Signature]
28/11/21
AE

[Signature]
28-01-21
EE

Signature

(Name of Inspector)

[Signature]
28/1/2021

[Signature]
28/01/2021
J-E