

1
Name of work -
Situation of work -
Agency by which work is executed -
Date of measurement -
No. and date of agreement

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Restoration of traffic from Arkhanna PM Bypass to Chandabali Santkal toll.					
Charge head - 2245					
Authority:- RWD letter 40-2789 dated 21/08/2020 and verbal order of EE RWD Phandaha					
Agency:- Bhenu pratap Singh Basant Bihari Talgami purnea					

Date of Entry:- 30/11/2020					
RECORD ENTRY					
① providing Brick bats including spreading laying compacting					
do					
125m	X	$\frac{2.11 + 4.55}{2}$	X	$\frac{2.0 + 2.60}{2}$	$\frac{2.60 + 2.70}{2}$
				$+ \frac{2.30}{5}$	m
$= 125m \times 3.33m \times 2.64m = 1015.65m^3$					
38m	X	$\frac{0.89 + 3.15}{2}$	X	$\frac{1.60 + 2.9 + 2.3}{2}$	$\frac{2.8 + 2.9 + 1.1}{6}$
					m
$= 38m \times 2.02m \times 2.27m$					
Continuation = 173.99m ³					

2
Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
33.25	1.5	2.95	1.5	1.4	
	2			2	
= 33.25	2.225	1.45			$107.27 m^3$
35m	0.62	2.27	1.4	1.6	
	2			1.7	
				0.9	
				4	
= 35m	1.445	1.65			$83.45 m^3$
Total =					$1380.36 m^3$

① Labour for driving 62 mm to 75 mm dia bamboo poles including cutting in proper size and

Shoes etc - - - do - -

- - - do - - -

194 - 653

0.3

Required value = $\frac{653 \times 4}{0.3}$

= 8707

③ Supplying fitting & fixing of bamboo 62 mm to 75 mm do -

do - - -

Qty = $8 \times 653 m = 5224 m$

④ Supplying fitting and fixing in portion - - - do - - -

Qty = $653 \times 1.54 = 999.5 m^2$

30/11/2020

Executive Engineer
Rural Works Department

261

ne

Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B	D.	
<u>ABSTRACT OF COST</u>					
① providing Brick bats					
including Spreading Laying					
Compacting -- do --					
-- do --					
(vide TMB - page - 02)					
Qty = 1380.86 m ³					
@ Rs 1717.37/m ³ Rs 2370588 =					
② Labour for doing 62 mm					
to 75 mm dia bamboo					
pile -- do --					
-- do --					
(vide TMB - page - 02)					
Qty = 8707 m					
@ Rs 26.35/m Rs 229429 =					
③ Supplying fitting and					
fixing of bamboo 62 mm					
to 75 mm dia Runner					
fixed at every vertical					
pile -- do --					
(vide TMB - page - 02)					
Qty = 5224 m					
@ Rs 4.59/m Rs 23978 = 0					

Continuation

~~104ml
01/02/2021
JH~~

Scanned by CamScanner

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhandaha

2. Name of Block/Road- Barhara Kethi / Asbanna PMGSY Road to Chandraki Santhal
tola

A. For Road

1. Damage Location/Chainage :
2. Damage Length : 231.25 M
3. Nature of Damage : slope damage due to direct beat of River
4. Details of Restoration :
 - i. Material being used in Restoration Bamboo, Brick bats
 - ii. Equipment/Tools being used in Restoration works: Tractor
 - iii. Procedure taken up in Restoration works : Manual
 - iv. Restored Length : 231.25 m

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
 - i. Material being used in Restoration :
 - ii. Equipment/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
28/1/2021
JE

28/01/21
EE

Signature

(Name of Inspector)

[Signature]
28/1/2021

SAS f
28/01/2021
J.E.