

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Scanned by CamScanner

Schedule XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT				
① providing brick bats including spreading laying compacting					
--- do --- do ---					
TMB - Page - 01					$= 393.75 \text{ m}^3$
@ 1717.37/m ³					$= 6,76,214.43 = \text{Rs}$
Total					$= 6,76,214.43 = \text{Rs}$
Add GST @ 12%					$= 81,145.73 = \text{Rs}$
Add labour cost @ 1%					$= 67,621.14 = \text{Rs}$
Total					$= 7,64,981.30 = \text{Rs}$
Add signature fee @ 10%					$= 41,800 = \text{Rs}$
Total					$= 8,05,922 = \text{Rs}$

100m²
01/02/2024
J12

Inspection Report for Flood damage work

Date:

1. Name of PIUs- *Phandaha*

2. Name of Block/Road- *Borahara Kothi/Hannuman Nagar chakla to Bhatsara Road*

A. For Road

1. Damage Location/Chainage :

2. Damage Length : *17.00 M*

3. Nature of Damage : *washout due to flood*

4. Details of Restoration :

i Material being used in Restoration : *bricks bats, Bamboo*

ii Equipment/Tools being used in Restoration works: *Tractor*

iii Procedure taken up in Restoration works : *Manual*

iv Restored Length : *17.00 M*

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE/AE/EE

[Signature]
28/1/21
EE

Signature

(Name of Inspector)

[Signature]
28/1/2021

SSS
28/01/2021
J.E.