

FD 8 (2020-21)

M.B.No- 25

Schedule XLV-Form No. 134

Kurmi Tola to Dumar Tola DIVISION

SUB-DIVISION

Block - Dhamdaha

Measurement Book

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF WORK:- Restoration of Road Kurni Tola To Dumar Tola.					
Authority:- E. E. R. W. D. Works Division, Dhamdaha.					
1 - Supply, Fitting and fixing of bamboo 62 mm to 75 mm dia					
B x B4 = 672 mtr.					
2 - Labour for driving Bamboo Piles					
25.20 Mtr Length = 1120 Mtr.					

3 - fitting and fixing Bamboo woven checkers B4 mtr x 1.50 m					
					= 126 mtr
4 - supply and spreading of Bitum Batl					
CH - 2720 mtr					
R/s - B M x (2.70 + 4.75) m					
					x (2.0 + 2.10) = 61.09 m ³
R/s - 10.30 m x (3.20 + 4.65)					
					x (1.40 + 1.50)
					= 58.62 m ³

Continuation
 = 119.72 m³

Executive Engineer,
Rural Works Department
-Works Division Bhambaha (Pune)

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3/3 Supply, fitting and fixing of Bamboo (62 mm to 75 mm) dia 672 meter o/p.					
0.1 item N. (0.1)					
0.1 4 = 51/100					
					30842
4/4 Supply, fitting and Bamboo (chunby 126 M ² Qty vide 04 P-0 L 1-cm N. (3) 0.1-					
22 12 69 / M ² 27,9332					
					B-4,34,4352

Add 12% G.S.T —	(+)	52,1322
Add 1% L.C.D —	(+)	43442
Add 5 Fee —	(+)	25,0002
Total B —		2,13,91120

Remainder
26-02-2021
(0.10)

Continuation

Inspection Report for flood damage work

Date:

1. Name of PUs: Bhamdaha

2. Name of Block/Road: Kurm Tolga to Dumar Tolga

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 30.40 m

3. Nature of Damage :

4. Details of Restoration : slope damage due to flood

i Material being used in Restoration

Barbed

ii Equipment/Tools being used in Restoration works:

Tractor

iii Procedure taken up in Restoration works

Manual

iv Restored Length

30.40 m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

Pranay
29-1-22
Signature of JE/AE/EE

27/1/22
or

27/01/22
EG

Pranay
29/1/2021
Signature
(Name of Inspector)