

FDR (2020-21) MB.No - 32
Schedule XLV-Form No. 134

CHAH DODA to MOHNA

DIVISION

SUB-DIVISION

Block - Dharmdaha

Measurement Book

Executive Engineer
Rural Works Department
Works Division Dharmadaha (Pune)

Mike	h	44,328	=
------	---	--------	---

17	17 = 37	17	h. 452,7742
----	---------	----	-------------

Continuation

11-5,04,10220

Inspection Report for flood damage work

Date:

1. Name of PIUs. *Phandaha*

2. Name of Block/Road. *Phandaha/ Chandwa to Mohna*

A. For Road

1. Damage Location/Chainage :

2. Damage Length : *78.6 M*

3. Nature of Damage : *washout due to flood*

4. Details of Restoration :

i. Material being used in Restoration

: *brick bats, Hume pipe*

ii. Equipment/Tools being used in Restoration works:

: *Tractor*

iii. Procedure taken up in Restoration works

: *Manual*

iv. Restored Length

: *78.6 M*

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i. Material being used in Restoration

ii. Equipment/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works

iv. Restored Length

10/01/21
Signature of JE/AE/EE

28/1/21
AE -

28.01.21
EC

Signature *28/1/21*
(Name of Inspector)

Scanned with Cam