

FDR (2020-21)

MR.No- 20

Schedule XLV-Form No. 134

Chanduo Petrol Pump & to Sabariya

DIVISION

SUB-DIVISION

Block - Dhamsdaha

Measurement Book

Name to work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF WORK: Restoration of Road From Chaudhari Petrol Pump to Samiya under F.D.R.					
Authority: G.E.R.W.D. Works Division Dhamdaha					
1- Supply, fitting and fixing of Bamboo 62 mm to 75 mm dia					
B x 25.0 = 200 m ²					
2- Labour for driving 62 mm to 75 mm dia					

Bamboo Piles					
15.0 m ² Length = 333 m ²					
2- Supply, fitting and fixing of Bamboo woven charhary 25 m x 1.5 m = 375 m ²					
4- Providing and labour for placing of empty cement bags					
15 m x 1 m x 0.8 m = 12 m ²					
12 / 0.3398					
= 352 bags					
111 to 350 bags					
5- Providing and spreading Brick bats					
CH-2100 m - R/S					

Continuation

Particulars	Details of actual measurement				Contents of iron
	No.	L.	B.	D.	
R 7.50 M X (2.70 + 0.90) H					
		2			
X (1.50 + 2.40 + 1.80) M					$= 92.33 \text{ M}^3$
		3			
R/S 2 M X (2.70 + 7.50) M X					
		2			
(1.5 + 1.9) H					$= 47.67$
		2			
CH-2500 M					
12 M X (3.23 + 0.43) H					
		2			
X (2.0 + 3.10 + 3.90 + 2.20) H					
		4			
					$= 222.76 \text{ M}^3$
					$T = 363.69 \text{ M}^3$

6- Providing and Laying
R.C.C Pipe Dia 1000
mm (ø)
6 N^o X 2.50 M = 15.00 M³

7- Providing and spreading
Brick Bath
12 M X (2.77 + 0.43)
2
X (2.80 + 2.90 + 2.80)
3
 $= 224.39 \text{ M}^3$

Less H. like Qty = 115.57 M³
T = 208.82 M³

Human
20-11-2020
(S.A)

Continuation

05.12.2020
Executive Engineer,
Rural Works Department

Particulars	Details of actual measurement				Contents of area
	No	I	II	D.	
(ABSTRACT OF COST)					
1/4 Supply, fitting and fixing of Bamboo 200 miter on P.O.					
Item No. (01) @					
B. 42 59/MTL					B. 9182-
2/3 Labour for driving					
62 mm to 75 mm dia Bamboo fillet					
333 miter by vide					
on P.O. Item No.					
(02) @					
26 235/MTL B.					87752-

3/4 Supply fitting and fixing of Bamboo					
Wovra Charkay					
37.5 M ² on P.O.					
Item No. (03) @					
B. 14 55/M ²					
221 69/M ² B.					83191
4/2 Labour for filling					
Cement base, slabs and Laying materials					
350 base on P.O.					
Item No. (04) @					
B. 302 60/base					
					B. 10,7102-

Continuation

B. 28,7260-

	(a) U -	4432	=	88	
		MTH		V	664922
	Total U -	1078	,	4192.	
Add G.S.T 12% — (+)		129	,	410.~	
Add Labour cost 4% & 7% —		10	,	7842.	
Add S. Fee — (+)		60	,	7002	
	Total -	12	,	79,2132	
	U.	12,	79,2132		
Panna					
26-02-2021					
(JK)					

Scanned with CamScanner

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha

2. Name of Block/Road- Chandwa petrol pump to Sabaiya

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 31.50m

3. Nature of Damage :

4. Details of Restoration : slope and Top of the Road fully washed out due to flood.

i. Material being used in Restoration :

Brick Bats, Hume Pipe

ii. Equipment/Tools being used in Restoration works:

Tractor

iii. Procedure taken up in Restoration works :

Manual

iv. Restored Length :

31.50m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i. Material being used in Restoration :

ii. Equipment/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Pranav
27-07-21
Signature of JE/AE/EE

27/7/21
OC

27-1-21
CC

Pranav
27/7/2021
Signature
(Name of Inspector)