

FD R (2020-21)

MO. NO - 21

Schedule XIV-Form No.-134

Bangali Tola to Dumariya DIVISION

(Dumaili SBI Bank) SUB-DIVISION

MEASUREMENT BOOK

Block - Dhandahla

1
 Name of Work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement -
 (These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF WORK:- Restoration of Road from Bangali Tola To Dameli SBT BANK Under F.D.R.					
Authority:- E.C.R.W.D WORK Division, Dhauradaha.					
1- supply, fitting of Bamboo (62 mm to 75 mm) dia					
B X 59.0 M = 472 Mtr.					
2- Labour For driving 62 mm to 75 dia Bamboo Piles					
17.80 M Length = 787 Mtr.					
3- fitting and fixing of Bamboo woven chanday					
59.0 M X 1.50 M = 88.5 M ²					
4- Providing and Labour for placing of empty cement bags.					
17.80 M X 1.5 M X 1.0 M = 26.7 M ³					
13.20 M X 1.5 M X 1.0 M = 19.8 M ³					
Total- 46.5 M ³					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
No of bagl =	46.2				1409
			0.033		bags
5- Providing and Laying					
R.C.C Pipe N/3					
Low ϕ (mm) in single					
R.C.C					
2 N/3 x 2.50 M =					5.0 M ²
6 Providing, supply and					
Spreading of Brick					
bats					
130 M -	5 M X	(4.05 + 5.28) M			
		2			
	X	(1.20 + 1.40 + 1.10) M			
		3			
					= 28.77 M ³
500 M -	11.50 M X	(2.08 + 5.24) M			
		2			
	X	(2.50 + 3.70 + 3.30) M			
		3			
					= 133.29 M ³
16.30 M X	(1.07 + 2.37) M				
		2			
	X	(1.30 + 1.40 + 1.20 + 1.30) M			
		4			
					= 36.45 M ³
					T = 198.51 M ³
Less for h.p. Qty =					5.19 M ³
					T = 193.32 M ³

Pruman
29/11-2020
(J.E)

Continuation
29/11/20
J.E

20.12.20
Executive Engineer
Rural Works Department
Works Division Dhamdaha (Pura)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(ABSTRACT OF COST)					
1/1 Providing, spreading Laying Brick Batt 193.32 m ² Qty vide on P-02 Item No (06) @ 1717.37 Rs. 332,002.2					
2/2 Labour for filling Cement bag 140g bag Qty vide on P-02 Item No (04) @ 11.					
30 @ 60% each Rs. 42,228.2					
3/3 Labour for driving 62 mm to 75 mm dia Bamboo Piles 7 B7 Miter Qty vide on P-01 Item No (02) @ 11. 26 = 35/Miter 11 Rs. 20,737.2					
4/4 Supply, fitting of Bamboo 472 miter Qty vide on P-02 Item No (01) @ 11. 4259 Miter Rs. 2166.2 Rs. 3,97,133.2					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5/5 Supply, fitting and fixing of claychay					
BB. 5 m ² on 1-00 item					
N. 65 @ 11.					
22 12 60 / m ²					B- 196262
6/6 providing and laying R.C.C. Pipe NPS					
1000 mm (Ø) 5.0					
miter on 1-02 item					
N. 65 @ 11.					
44322 B3 / miter					
					B- 22,1642.
					B- 4,38,9172
Add 12% Cr. & T					+ 52,67020
Add labour cell 1%					+ 438920
Add S. Price					+ 2050020
					5,16,49620
Planned 26-02-20 G.E.					B- 5,16,49620

Continuation

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha

2. Name of Block/Road- Bangali Tola to Dumariya (Domaili) SBI Bank

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 32.80 m

3. Nature of Damage : slope damage due to flood

4. Details of Restoration :

i Material being used in Restoration

: Brick Bats

ii Equipment/Tools being used in Restoration works:

: Tractor

iii Procedure taken up in Restoration works

: Manual

iv Restored Length

: 32.80 m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

:

ii Equipment/Tools being used in Restoration works:

:

iii Procedure taken up in Restoration works

:

iv Restored Length

:

P. Kumar
28-01-21
(I.E.)
Signature of JE/AE/EE

28-01-21
EE

28-01-21
EE

P. Kumar
28-01-21
Signature
(Name of Inspector)