

FIR (2020-21) *N.B.No-26*
Schedule XLV-Form No. 134

Bhotiya Nibniya Road **DIVISION**

Palkriya Tola **SUB-DIVISION**

Blaer - Phampals.

Measurement Book

Name to work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement—
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
NAME of Work: Reddation of Road from Bholiya Nidariya Road to Pakanga Tola.					
Authority: E. C. R. & D. Works Division, Dhanda.					
1 - Supply and spreading Brick Ball in Ditches at G.M.H.					
L/S - $6M \times (1.20 + 1.30)M \times 0.50M$					
	2				$= 5.75M^3$
R/S - $BM \times (1.20 + 1.40 + 1.0) \times 1.20$					
	3				

				$\times 0.50M$	$4.80M^3$
L/S - $6.10M \times (1.80 + 1.60)M \times 0.50$					
	2				$= 5.19M^3$
R/S - $2.10M \times (1.30 + 1.50)M \times 0.50M$					
	2				$= 1.47M^3$
L/S - $7.10M \times (1.50 + 1.60)M \times 0.50M$					
	2				$= 5.50M^3$
R/S - $4.50M \times (1.50 + 1.60 + 1.40)M$					
	3				
				$\times 0.30$	$= 2.03M^3$
R/S - $5M \times (1.30 + 1.40) \times 0.60M$					
	2				$= 4.05M^3$
R/S - $3M \times (1.30 + 1.40)M \times 0.20M$					
	2				$= 0.81M^3$
R/S - $3.60M \times (1.30 + 1.40) \times 0.15M$					
					$= 0.75$
Continuation					
T - $28.33M^3$					

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
R/S- 1x 2.20m x 1.20m					4.20m ²
				2	
16.00m				x 1.5m	0.57m ²
R/S- 1.5m x 1.30m					1.95m ²
				2	
				x (1.30 + 1.40 + 1.50)	
				3	
2/2				Total	= 29.70m ²
Labour for filling cement bag					58.69m ²
30.11.20				24 69 bags	
(J.E)					
30.12.20					
Executive Engineer					
Rural Works Department					
Works Division Dhamdaha (Purnea)					

(ABSTRACT OF COST)					
1/1 Construction of					
embankment (supply					
and spreading Brick					
Bats in Ditch)					
58.69m ² Qty vidal					
58.60m ² P-02 item					
(01) @ 11.238702					
m ²					
U. 1,39,879.					
2/2 Labour for filling					
cement bag supply					
and Laying 4.69 bags					
Qty of P-02 item					
No. - 02 @ 11.238702					
Continuation					
U. 1,39,879.					

VF-31, 32, 8792

[illegible]

Inspection Report for flood damage work

Date:

1. Name of PIUs- B Dhamdaha

2. Name of Block/Road- Bhotiya Hibniya Road to Pakaraya Tolg

A. For Road

1. Damage Location/Chainage :
2. Damage Length : 63.20 m
3. Nature of Damage : Slope cutting due to flood.
4. Details of Restoration :
 - i Material being used in Restoration : Brick bats
 - ii Equipment/Tools being used in Restoration works: Tractor
 - iii Procedure taken up in Restoration works : MGM
 - iv Restored Length : 63.20 m

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
 - i Material being used in Restoration :
 - ii Equipment/Tools being used in Restoration works:
 - iii Procedure taken up in Restoration works :
 - iv Restored Length :

28-01-22
Signature of JE/AE/EE

28/1/22
on

28-01-22
EC

28/1/22
Signature
(Name of Inspector)