

FDR (2020-21)

198.40-22

Schedule XLV-Form No.-134

Dakaita Dih Tola To Dakaita^H DIVISION

Main Road.

SUB-DIVISION

MEASUREMENT BOOK

Block - Dharmdaks

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement -

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME of WORK:- Restoration of Road from Dakaita Dih Tola to Dakaita main Road.					
Authority:- E. E RWD WORK Division, Dhamdaha.					
1- Supply, fitting and fixing of Bamboo (62 mm to 75 mm) dia					
B x 277.0 m = 3016 Mtr.					
2- Labour for driving Bamboo Piles.					
112 mtr length = 5027 Mtr.					
3- Supply, fitting and fixing of Bamboo woven charchary.					
377 m x 1.50 m = 565.5 m ²					
4- Providing and Labour for placing of empty cement bag					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1X 58M X 2M X 1.0 M					116 M ³
1X 112M X 1M X 2.0 M					224 M ³
					T - 340 M ³
No of bag					
= 340					
0.03398					= 10005 bag
5 - supply and spreading of B.M.C.R ball					
CH-530 M					
1X 54.40 M X (4.78 + 0.06) M					
				2	
X (1.40 + 2.60 + 2.80 + 2.10 + 1.80)				5	

					= 805.59 M ³
3 M X 2 M X 0.5					3 M ³
18 M X (1.77 + 2.84) M				2	
X (1.20 + 0.90 + 1.10)				3	= 44.26 M ³
35 M X (1.77 + 2.79) M				2	
(1.0 + 0.80 + 0.90 + 1.40)				4	= 81.80 M ³
39 M X (2.70 + 3.98)				2	
X (0.90 + 1.40 + 1.60 + 1.20) M				4	= 166.08 M ³
Total					= 1097.74 M ³

From
29-11-2020
(J.E)

Signature

05-12-20
Executive Engineer,
Rural Works Department
Works Division Dhamdaha (Pune)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(ABSTRACT OF COST)					
1/1 Providing, Laying and Spreading Brick					
Batch 10 97.74 M ³					
on P-02 Item 11.					
(05) @ 11.					
17 17 = 37 / M ³					
					Rs. 1885.2262
2/2 Labour for filling Cement Bag					
10005 bags 0.5					
vide on P-02					
Item No (04) @					
Rs. 30 260/each					
					Rs. 306153
3/3 Labour for driving 62 mm to 75 mm dia Bamboo Piles					
5027 niter on P-02					
Item No (02) @					
Rs. 26 = 35/each					
					Rs. 1,32,461
4/4 supply, filling & fixing of Bamboo Chundchung					
3016 niter on P-02					
					Rs. 23,238.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	1	2	3	
Q. 1. No. 4	1.5	3/4	1/4	1/4	13,843
5/5	Supply, fitting and				
	fixing 568.5 m ²				
	On P-02 item				
	No. (03) Q. 1.				
	22	12.63	1/4	1/4	1,253,662
				1/4	24,23,949
				1/4	24,23,949
Add 12% G. & T					(+12,93,905)
Add Labour (28%)					(+12,44,920)
Add S. Fee					(+11,25,000)
					Total - 12,892,603.2
					29,08,000.2
Prima					
24-02-2021					
(JE)					

Continuation

Inspection Report for flood damage work

Date:

1. Name of PIUs- Dhamdaha.

2. Name of Block/Road- Dakaita Dih Tolg To Dakaita Main Road

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 146.40m

3. Nature of Damage : Slope and Top fully damaged due to direct hit of river.

4. Details of Restoration :

i Material being used in Restoration

: Barck bats

ii Equipment/Tools being used in Restoration works:

: Tractor

iii Procedure taken up in Restoration works

: Manual

iv Restored Length

: 146.40m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

:

ii Equipment/Tools being used in Restoration works:

:

iii Procedure taken up in Restoration works

:

iv Restored Length

:

Pruman
28-01-21.
Signature of JE/AE/EE

28/1/21
DC

28-01-21.
EE

Signature Pruman
28/1/21
(Name of Inspector)