

FDR (2020-21) N.B.No-33
Schedule XLV-Form No. 134

CHANDRA MOHAN TO

DIVISION

BASHA NUSHARJ

SUB-DIVISION

Block - Pharmacy

Measurement Book

Name to work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF WORK: Restoration of Road Chandwa Mohana to Batta Muthani.					
Authority: G. P. R. W. D.					
Work Division, Dhamdaha.					
1- supply, fitting and fixing of Bamboo (62 mm to 75 mm)					
B x 49.0 = 392 mtr.					
2- Labour for driving 62 mm to 75 mm dia					

Bamboo Piles					
14.80 mtr length - 653 mtr.					
3- fixing Bamboo woven chanchary.					
49.0 mtr x 1.50 m = 73.5 m ²					
4- supply and spreading of Brick Ball					
L/s - B M x $\frac{(1.58 + 3.08)}{2}$ m					
x $\frac{(1.50 + 1.60 + 1.40)}{3}$ m					
= 27.96 m ³					
L/s - 25 m x $\frac{(1.70 + 3.13)}{2}$ m					
x $\frac{(1.20 + 1.80 + 1.50)}{3}$ m					
= 86.54 m ³					
Continuation					

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
R/S 21M x (1.35 + 2.05)M		2			
x (1.50 + 1.85 + 1.45)M		3			
					= 72.24M ³
L/S 38.60M x (1.93 + 3.31)M		2			
x (1.60 + 1.40 + 1.60 + 0.90)		4			
					= 139.06M ³
L/S 16M x (1.55 + 3.82) x		2			
(1.90 + 3.10 + 1.80)		3			= 97.38M ³

R/S - 38M x (1.80 + 2.92)		2			
x (0.80 + 1.70 + 0.90)		3			= 101.63M ³
R/S - 41M x (2.22 + 3.63)M		2			
x (1.20 + 1.90 + 1.10)		3			= 168.18M ³
					T2 693.21M ³

P. Kumar
22-11-2020
(J.B)

AS
20/11/20
A.E

Executive Engineer.

Continuity Works Department
Works Division Dhamdaha (Pune)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(ABSTRACT OF COST)					
1/1 Providing, Laying					
spreading of					
Brick Bats					
693.21 M ² Qty					
vide on P. 02 item					
N. (04) @ 1/1					
17 17 = 37					
MB					Rs-1190498-
2/2 Labour for driving					
(62 mm to 75 mm)					
dia Bamboo P./d					
653 Mtr on P.					
01 item N. (02)					

@ 1/1 - 26235
Mtr 1/1 17207

3/3 Supply, fitting
and fixing of Bam
boo 392 Mtr on P.
P. 01 item N.
(02) @ 1/1 - 4259
Mtr 1/1 17992

4/4 fixing of Bamboo work
charging 73.5 M² on
P. 01 item N. (03)
@ 1/1 - 22 12 69
M²
1/1 16294

Continuation

1/1 1225798

Inspection Report for flood damage work

Date:

1. Name of PIUs-

Dhamdaha

2. Name of Block/Road-

Chandwa Mohan to Basha Mustari

A. For Road

1. Damage Location/Chainage :

2. Damage Length : 187.60 m

3. Nature of Damage :

4. Details of Restoration : both side slope damage due to Rainwater

i Material being used in Restoration :

Bord Cut

ii Equipment/Tools being used in Restoration works:

Tractor

iii Procedure taken up in Restoration works :

Manual

iv Restored Length :

187.60 m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

Prumona
27-01-2021

Signature of JE/AE/EE

27/1/21
27

27-01-21
27

Signature

(Name of Inspector)