

FDR

Schedule XLY-Form No. 134

217-11 217-115-2122921-2172921

2172921

2172921

2172921

DIVISION

SUB-DIVISION

MEASUREMENT BOOK

4205 ÷ 1944111712

MB No ÷ 1251

प्रमाणित किया जाता है कि इसकी
पुस्तक में कुछ मशीन प्रिंट 100/100
सो पन्ने हैं जिसे सहायक अभियंता
श्री अरविन्द कुमार भा.
प्रमंडल विद्यापीठ नगर के नाक से
निर्गत किया जाता है।

29.9.20
कार्यपालक अभियंता
वाणिज्यिक कार्य विभाग
विद्युत निगम पटवरी (समस्तीपुर)
29.9.20

FDR
Sch. XLV - Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No. 1251

FDR

Name of Officer श्री अरविन्द कुमार भा.
विद्यापीठ नगर

Date of first entry _____

Date of last entry _____

1st & Final Bill

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Repair of Flood damaged in Shakti under Saraswati Chowk to Ministry					
Agency - Bhagwati Construction					
Ag. No -					
Date of entry - 16-10-2020					
Items of work					
① Laying Brick Batt on					
Prepared Soil Surface of damaged stretch - do - all comp. Job.					
61 nos	18m	1.150m	0.600		12.42
01	45	1.250	0.450		25.31
01	22	1.500	0.300		9.90
01	35	1.250	0.300		13.13
01	55	1.15	0.150		9.49
02	30	1.175	0.300		21.15
01	24	1.175	0.300		8.46
02	30	1.125	0.450		30.37
02	30	1.650	0.600		59.40
01	02	1.650	0.600		1.98
01	26	1.250	0.300		9.75
61	30	0.450	1.600		21.60

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	01	30	1.225	0.600	= 22.05
	01	20	1.225	0.600	= 14.70
	01	02	1.600	0.450	= 1.44
	01	12	1.20	0.500	= 9.00
				Total	= 270.15 m ³
02] Contt. of G.S.B - Gr-II					
by Providing well graded material in uniform layers - Rolling & Compacting - do - do					
In Damaged Portion of the Road					
	02	30	1.70	0.175	= 17.85
	01	25	1.700	0.175	= 7.43
	01	30	1.25	0.175	= 6.56
	01	20	1.25	0.175	= 4.37
	02	30	2.00	0.175	= 21.00
	02	30	1.500	0.175	= 15.75
	01	10	1.500	0.175	= 2.62
	04	30	1.95	0.175	= 40.95
	01	05	1.450	0.175	= 1.26
	01	30	1.45	0.175	= 7.61
	04	30	1.85	0.175	= 38.85

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	01	20	1.85	0.175	= 6.47
				Total	= 170.72 m ³
[03] Providing, Laying, Spreading & Compacting 40mm - 60mm in damaged Portion of the Road --- do --- 911 Comp. Job.					
	01	20	1.8	0.075	= 2.55
	02	30	1.650	0.075	= 7.425
	01	30	1.100	0.075	= 2.47
	01	08	1.80	0.075	= 1.08
	01	24	1.100	0.075	= 1.98
	01	20	1.45	0.075	= 2.175
	01	05	1.45	0.075	= 0.543
	01	30	1.35	0.075	= 3.03
	01	08	1.35	0.075	= 0.810
	03	30	1.800	0.075	= 12.15
	01	06	1.80	0.075	= 0.81
	02	30	2.15	0.075	= 9.67
	01	10	2.15	0.075	= 1.61
	01	30	1.600	0.075	= 3.60
	01	21	1.600	0.075	= 2.52
	05	30	1.90	0.075	= 21.37
	01	10	1.90	0.075	= 1.42
	11	05	1.75	0.075	= 7.21

Continuation

~~Ravi~~
~~16-10-2020~~
~~J.E~~

871
16.10.2022
NE

Abstract of art

[01] Laying Brick Balls
on Prepared Soil
Surface of damaged
Patch.

Vide-Page no 02

$$= 270.15 \text{ N} \cdot 3$$

(a) $71680 = 02/173$

~~7453857~~ = 00

[02] Const. of G.S.B - G.M.
by D/V well graded
metallurgical - do - do

eg. Vide - Page no-03

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		= 170.72 m ³			
@ ₹ 2035 = 66/m ³					
					₹ 347528 = 00
[03] Providing, Laying Spreading & Compacting - - do - all					
Comp. Job.					
Qty. Vide Page no - 04					
		= 104.40 cu-m			
@ ₹ 3166 = 72/m ³					
					₹ 330606 = 00
					Total = ₹ 1131991 = 00
Add 12% GST H/135839 = 00					
Add 1% L.C. C/H 11320 = 00					
Add Signage & fee C/H 16500 = 00					
Total: ₹ 1295650 = 00					
Less 10% below C/H ₹ 129565 = 00					
Ref 000 (Rate)					
Ravi 16-10-2020 J.C.					
15/10/2020 AE					
c.s.b. 22-2-21					

Continuation