

Inspection Report for flood damage work

Date:

1. Name of PIUs- *Dhanda*

2. Name of Block/Road- *Raupauli/ Garib ghat More to Chharapatti*

A. For Road

1. Damage Location/Chainage :

2. Damage Length : *47.0 M*

3. Nature of Damage : *Side cutting due to flood*

4. Details of Restoration :

i Material being used in Restoration

: *Brick bats*

ii Equipment/Tools being used in Restoration works:

: *Tractor*

iii Procedure taken up in Restoration works

: *Manual*

iv Restored Length

: *47.0 M*

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

:

ii Equipment/Tools being used in Restoration works:

:

iii Procedure taken up in Restoration works

:

iv Restored Length

:

Sh 27/01/2021
Signature of JE/AE/EE

Sh 27/1/21
AE

G 27-1-21
EG

Sh 27/1/2021
Signature

(Name of Inspector)

Dhamdaha DIVISION

Rupauli SUB-DIVISION

Gorib Ghat mare to charapatti

Measurement Book

No. - 47.

आपति किना जाता है कि इस मापी
पुस्त में मुद्रित 1 से 100 पन्ने हैं यह
मापी पुस्त अवर समस्त पदाधिकारी

Name of Officer

रूपाली के नाम निम्न लिखा जाता है।

Date of first entry

12-10-20

Date of last entry

Executive Engineer,

Rural Works Department

Works Division Dhamdaha (Purnea)

12/10/20

Date: _____
 me o Situation of Work- _____
 Agency by which work is executed- _____
 Date of Measurement- _____
 No. and date of agreement _____
 (These four lines should be repeated at the commencement of the measurement relating to each work)


Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/2 work. For to bridge at road to Chharguati					
Authority - E.C. Road (NO) Division - Mandak.					
① Providing and laying broken bnts in ditches including cutting of bnts with hammer. Probable cost of supply bnts do - do - emp. Jos.					
top width 15 X (2.10 + 1.90 + 1.80)					
1 X 15 X (1.97 + 3.07) X (0.70 + 1.90 + 0.80)		2		3	
1 X 15 X 2.50 X 1.13					42.487 ³
top width 1 X 20 X (1.80 + 1.70 + 2.30)					
1 X 20 X (1.73 + 2.73) X (0.070 + 1.60 + 0.70)		2			
1 X 20 X 2.33 X 0.80					37.287 ³
top width 1 X 12 X (2.50 + 2.60 + 2.90)					
1 X 12 X (2.67 + 2.77) X (0.60 + 1.80 + 0.90)		2		3	
1 X 12 X 3.22 X 1.10					42.50
					122.267 ³

30/11/2020
 J.E.
 Continuation
 30/11/2020

Executive Engineer
 Rural Works Department
 Mandak.

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
<u>ABSTRACT OF COST</u>						
N/works - For the parapet road to Chhampalli						
Authority - E.E R.W.D.W. Division Dhankota						
① providing and Laying Bricks bats in ditches including temporary of bats						
122.26 m ³	p-	②				
@ 177.38/m ³	—	—		Ry	209,966	
@ 12% L.S.T	—	—		Ry.	25196	

@ 1% L. less				Ry.	2100 = 00
@ 10% Supervisory fee				Ry.	12900 = 00
				Ry	2,50,162 = 00


 26/02/2021
 J.E