

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st on Allotment & Final</u>					
* Name of work: Repair of Road from Hardiya to Pachgachhiya under FDP 224.					
* Agency: M.K.L Construction, village Semani, Bhawanipatna					

* Agreement with					
* Date of Commence: 21/06/2021.					
* Date of completion: 20/07/2021.					
* Rate — 0.02% below					
* Actual completion — 08/07/2021					
<u>Measurement</u>					
(1) Cons of Subgrade and earthen shoulders materials obtained from borrow pits —					
02 x 30.00 x 1.00 x 0.300					= 18.000
02 x 30.00 x 1.00 x 0.300					= 18.000
					/
	Total				36.000

Continuation

Sett. BUA Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	H	
					JE 0.9896=
Add. S. 13% →	⊕				59876=
Add. S. 12% →	⊕				4990=
Add. S. 11% →	⊕				7175=
					1
					571007=
Less 0.02% below →	⊖				114=
					570893=
(Signature) 08/07/2021 JE					

Material Statement

1) F/W →	36.50m ²
2) Stone mnd →	60.48m ²
3) Stone chips →	12.15m ²
4) Local Sand →	40.32m ²
5) Emulsion (SS-1) →	0.380m ²
6) Emulsion (PS-1) →	0.123m ²
7) Bitumen (8-90) →	0.855m ²
(Signature) 08/07/2021 JE	

Continuation