INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of 1	Inspection: 31/2/21 Dis	trict: Sarroll	
Division: Charles 2		7	
Name of	the Road: 706 - Khabsi tu	Bharkhuna (VI	(63-1
Scheme	Programme: PMC184		The second secon
SL No.	Parameters to be checked		Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		3
b)	Riding Quality		3
· c)	Road Camber		5
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		ed
e)	Contraction Joints provided or not (CC Pavement)		2
f)	Compaction of flank/slope & raincuts if any ation Remarks:- 9m 15m Longth of P.C. C Sworface. aggregetes		3
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		1g 3
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NV
c)	Condition of railings/slab/approach for Bridges		N.V
d)	Condition of Vent Clearance		C
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained		m S
Observ:	ation Remarks:-		
4.	Compliance History ATR. Submittedto SRCR VAR. h.s.		
a)	Status of ATR's & any others		
	of Officer: - Bindu fajou	Unsatisfactory (U)	IS
Design:	Legional Lab. Don	bhanga n.E.	Signature) 21/21