INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 30.07.2021		District: Myzafforba	r			
Division: MWSaffar por West Length (km): 1.70 cm						
Name of the Road: Loss Navharsaras To Gaussia via gaussara Mula tol (VP-31)						
Scheme/Programme: Routine Hauntemen eve						
Sl. No.	Parameters to be checked			Renarks (S/U)		
1.	Pavement OT					
a)	Condition of Surfacing			3		
b)	Riding Quality			3		
c)	Road Camber			1 11		
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			2		
e)	Contraction Joints provided or not (CC Pavement)		-	3		
f)	Compaction of flank/slope & raincuts if any			9		
Observation Remarks:-						
	Road Surface is in good Con hith as					
	U					
2.	Cross Drainage					
a)	Condition of head walls in Hume pip	e culverts including its painting		25.		
b)	Condition of Abutment & Wing walls	s, Slab in RCC culverts				
c)	Condition of railings/slab/approach for	or Bridges				
d)	Condition of Vent Clearance			_9		
Observation Remarks:-						
H.P. cul vort i's in gow londition						
3.	Road Furniture					
a)	Whether sign boards/informatory/castones/Pavement road markings are p		ع			
Observation Remarks: - Road Fermiture, Interruption Board, K.M. Port, rum PONS 1's d'xed in Road						
4.	Compliance History		T pla			
a)	Status of ATR's & any others					
Overall Rating :						

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:-	Ratnesh	Paswan	
Designature:-	F.E		

(Signature) E.E.