

INSPECTION REPORT FOR ROUTINE MAINTENANCE


Date of Inspection : 01/08/2021		District: Murzampur
Division : Murzampur Bazar		Length (km): 2.302 km.
Name of the Road: L104-Rampur-TOS to Bisimpur Manohar (V.R. 52)		
Scheme/Programme: Routine Maintenance		


Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement B-T	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road surface is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	S
Observation Remarks:- H.P. culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road furniture, Informatory Board, K.M. Pole & 200m Pole is done in road		
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) S

Name of Officer:- Ratnesh Paswan

Designature:- E.E


 01/08/2021
 AE


 1.8.21
 E-E