

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 31-07-2021		District: Muzaffarpur
Division : Muzaffarpur		Length (km): 5.01 km
Name of the Road: JAFARPUR ASLI-TEGPUR		
Scheme/Programme: Routine Maintenance		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
	BT	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- N/A
e)	Contraction Joints provided or not (CC Pavement)	- N/A
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- Road Surface is in good condition		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N/A
d)	Condition of Vent Clearance	S
Observation Remarks:- R.C.C. culvert is in good condition		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road Furniture, Informatory Board, k.m Post & 200 m Post is fixed in Road		
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:-

Ratnesh Paswan

Designature:-

R.P.

ARB/1
 31-07-2021
 AR

(Signature)

22/7/21
 31-7-21
 E.E.