

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 30.07.2021		District: Muzaffarpur
Division : Muzaffarpur West		Length (km): 2.55 km
Name of the Road: Bantapur Shakti Pith Maudir To Korrda NH-107, Main Bus		
Scheme/Programme: Routine Maintenance		Slab Tax
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- Road surface is in bad condition, Road crust is damaged. Pot developed in B.T. surface at ch. - 20m to 40m, 50m to 60m, 80m to 90m, 110m to 120m, 180m to 200m. and E.C. Pavement damaged at ch. 15m to 20m		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	N.A
Observation Remarks:- N.A		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Road Furniture. Informatory Board, K.M. Post a) 20m Post is down in Road		
4.	Compliance History	
a)	Status of ATR's & any others	ATR Not Complied
Overall Rating :		Satisfactory (S)/ Unsatisfactory (U)
Name of Officer:- Ratnesh Paswan		
Designature:- E.E		
Date: 30.07.2021 Signature: E.E		