

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: LO 48 KHAIRA SONO ROAD TO MANGE CHAPRI		
Hazards	Flood/Rain / 5 yr. Maintenance	
Division: JAMUI	District: JAMUI	Actual Length (in km): 3.80 KM
Damage Length (in km):	Damages Location/Chainage:	
Name of Scheme/Programme:	PMGSY	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: Maintenance work done satisfactorily.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: **KUMAR RAKESH**

Designation:

**तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना**

(Signature)

01.08.21