

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: L122 JAMUI KHARGPUR PWD ROAD VIJAY SAGAR TRACK-122

Hazards: Flood/Rain

Division: District: Actual Length (in km):

Damage Length (in km): Damages Location/Chainage:

Name of Scheme/Programme: PMGSY (OLD)

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
---------	--	-----------------

1.	Pavement (BT/CC)	S
----	------------------	---

a)	Condition of Surfacing	S
----	------------------------	---

Description of observation :

b)	Adequate Thickness of pavement layers constructed	—
----	---	---

Description of observation :

c)	Quality of Construction Material Used	—
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	Yes
----	--	-----

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	---

Description of observation :

2	Cross Drainage Structure
---	--------------------------

a)	Condition of head walls in Hume pipe culverts
----	---

b)	Condition of Vent Clearance
----	-----------------------------

c)	Condition of railings/Slab/approach for Bridges
----	---

Description of observation of CD works :

Remark if any: Road maintained properly.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

31.07.21