

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: BAHRAIN PWD ROAD TO BELDARI JAMUI LAKHISARAI PWD ROAD

Hazards: Flood/Rain / 5 Yr Maintenance

Division: District: Actual Length (in km): 6.00 km

Damage Length (in km): Damages Location/Chainage:

Name of Scheme/Programme: 3054 MR SHRENI-1 At Yr.

Status of Project: ☒ Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
---------	--	----------------

1.	Pavement (BT/CC)	<u>S</u>
----	------------------	----------

a)	Condition of Surfacing	<u>S</u>
----	------------------------	----------

Description of observation :

b)	Adequate Thickness of pavement layers constructed	<u>—</u>
----	---	----------

Description of observation :

c)	Quality of Construction Material Used	<u>—</u>
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	<u>YES</u>
----	--	------------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	<u>—</u>
----	--	----------

Description of observation :

2	Cross Drainage Structure
a)	Condition of head walls in Hume pipe culverts
b)	Condition of Vent Clearance
c)	Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: Maintenance of the road done satisfactorily.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

31.07.21