

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: BHANDRA PANPURWA PITCHROAD TO LAKHAY MAHAADALIT TOLA		
Hazards	Flood/Rain / 5 yr. Maintenance	
Division: JAMUI	District: JAMUI	Actual Length (in km): 2.40 km
Damage Length (in km):	Damages Location/Chainage:	
Name of Scheme/Programme:	SCP	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	U
a)	Condition of Surfacing	U
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	U
Description of observation :		
c)	Quality of Construction Material Used	U
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	U
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	U
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: ROAD CONDITION- Very poor and not maintained after completion of construction.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: **KUMAR RAKESH**

Designation: **तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना**

(Signature)

31.07.21