



# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 21/08/21		District: Saran
Division : Chapar 2		Length (km): 1.00
Name of the Road: Nagura Jaula Pur Road Se Surja Dev Singh Rachavida Yadav to Lupto Bhamihari Tika		
Scheme/Programme: M.M.C.Sy (Gen.)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N.A.
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) S

Name of Officer:- Binod Rajak  
Executive Engineer  
R.W.D.  
Regional Lab Darbhanga

  
21/08/21  
A.E.

(Signature)  01/08/21