

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 01/08/2021	District: Muzaffarpur
Division : Muzaffarpur West	Length (km): 2.05 km
Name of the Road: L032 Dichtaula to Pasumi Kapur (VR 28)	
Scheme/Programme:	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement BT	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-

Road surface is in good condition

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
d)	Condition of Vent Clearance	S

Observation Remarks:-

H.P. culvert is in good condition

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

Road Furniture, Informatory Board, Km. Post and 200m Post is fixed in road

4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Ratnesh Paswan

Signature:-

BR

ABY
01/08/2021
AB

22/2
1-8-21
(Signature) E-E