INSPECTION REPORT FOR ROUTINE MAINTENANCE

| Date of Inspection: 01-08-2021 District: Mulaffarbur | | |
|---|---|-------------------------|
| Division | : Museffector Most Length (km): 2,200 un | 7 |
| Name of the Road: Bagahi Malikana - Panaspur Mushahari Road Scheme/Programme: Doubbag Man Janey 2 | | |
| Scheme | Moythe May's former es | 2001 15 A 4000 9 7770 U |
| Sl. No. | Parameters to be checked | Remarks (S/U) |
| 1. | Pavement S.T | |
| a) | Condition of Surfacing | 3 |
| b) | Riding Quality | 3 |
| c) | Road Camber | 3 |
| d) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | 3 |
| e) | Contraction Joints provided or not (CC Pavement) | 9 |
| f) | Compaction of flank/slope & raincuts if any | 5 |
| Observ | Roed Surface 1/2 1'm good Con hithon | |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | NIA |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | 2 |
| (c) | Condition of railings/slab/approach for Bridges | NA |
| d) | Condition of Vent Clearance | 2 |
| Obser | R. C.O. Culver 1's in Son Continu | |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained | |
| Obser | vation Remarks: - Road Formiture. Informatory Board, 2W M Post 18 dixw i'm sou | Kim Port 4 |
| 4. | Compliance History | 3. 4 |
| a) | Status of ATR's & any others | <i>N</i> ·A |
| Ove | rall Rating : Satisfactory (S)/ Unsatisfactory (U) | ·S |

Name of Officer:-

Designature:-

Radnesh Paswan

(Signature)

E.E.