

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 01.08.2021 District: Sitamohi
 Division : Beland Length (km): 0.600
 Name of the Road: LOS3-PM65Y Road to Rajah Purnanand Nayak Tola
 Scheme/Programme: PM65Y

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	U
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	U
f)	Compaction of flank/slope & raincuts if any	

Observation Remarks:-

2.	Cross Drainage	No culvert
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Observation Remarks:-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U) Unsatisfactory (U)

Name of Officer:- Rana Babun Kumar Singh
 Designation:- Executive Engineer
 RWA Regional Laboratory Bhubaneswar.
 01.08.2021
 (Signature)