

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 31-07-2021	District: Sahamahi
Division : Beland	Length (km): 1.903
Name of the Road: LO72 - Beland Bypass No-01 to Machi Madhya Rd. (2nd & 3rd Km)	
Scheme/Programme:	PMGSY

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	U
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer: Rana Basant Kumar Singh
 Designation: Executive Engineer
 R.D., Regional Laboratory Bhopal

(Signature)