

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 01.08.2021		District: Sitamarhi
Division : Beland		Length (km): 1.416
Name of the Road: L073 - Pm6SY Path Jamua to Marpa Dhangar Tola.		
Scheme/Programme: Pm6SY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:-		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	U
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	U
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory (U)

Name of Officer:- Rana Basu Kumar Singh
 Designat re:- Executive Engineer
 RWD, Regional Laboratory Bhagalpur.

01.08.2021
 (Signature)