

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 31.07.2021		District: Sitamahi
Division : Beland		Length (km): 3.25
Name of the Road: Pachaur to Sukhi Road		
Scheme/Programme: MR-3054		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:-		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	No ATR.

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:- Rana Boun Kumar Singh  
 Designation:- Executive Engineer  
 RWD, Regional Laboratory, Bhopal.

(Signature)  
 31.07.2021