INSPECTION REPORT FOR ROUTINE MAINTENANCE

IVIGIAM	nspection: 31.07.2021 District: Sidamashi : Belland Lengtn (km): 0.900	
ame of	the Road: Patahi Googahi tola to TOI.	
cheme	Programme: GTSNY	
I. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	\mathcal{O}
Observ	ation Remarks:-	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	U
c)	Condition of railings/slab/approach for Bridges	
d)	Condition of Vent Clearance	ي
	Road Furniture	
3.	What is the first of the second of the secon	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained vation Remarks:-	U
a)	stones/Pavement road markings are provided and maintained	U
a) Obser	stones/Pavement road markings are provided and maintained	U NO ATR