

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: **JAMUI KHARAGPUR PWD ROAD TO BALWADIH (TRACK-107)**

Hazards: Flood/Rain / **5 Yr. MAINTENANCE**

Division: **JAMUI** District: **JAMUI** Actual Length (in km): **0.592 KM**

Damage Length (in km): Damages Location/Chainage:

Name of Scheme/Programme: **PMGSY (OLD)**

Status of Project: **Under Agreement/Out of Agreement**

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
---------	--	-----------------

1.	Pavement (BT/CC)	S
----	------------------	----------

a)	Condition of Surfacing	S
----	------------------------	----------

Description of observation :

b)	Adequate Thickness of pavement layers constructed	—
----	---	----------

Description of observation :

c)	Quality of Construction Material Used	—
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	YES
----	---	------------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	----------

Description of observation :

2	Cross Drainage Structure
---	--------------------------

a)	Condition of head walls in Hume pipe culverts
----	---

b)	Condition of Vent Clearance
----	-----------------------------

C)	Condition of railings/Slab/approach for Bridges
----	---

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	----------

Name of Officer: **KUMAR RAKESH**

Designation:

**तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना**

(Signature)

31.07.21