

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 30.07.2021	District: Si Yamachi
Division: Balesar	Length (km): 3.7
Name of the Road: Repair of road from Bhangura to Tikauli	
Scheme/Programme: NP 3054	

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:- No raincuts.

Sl. No.	Parameters to be checked	Remarks (S/U)
2.	Cross Drainage	No culverts
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—

Observation Remarks:-

Sl. No.	Parameters to be checked	Remarks (S/U)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

Sl. No.	Parameters to be checked	Remarks (S/U)
4.	Compliance History	No ATR
a)	Status of ATR's & any others	

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) Satisfactory (S)

Name of Officer:- Rana Bhogen Kumar Singh
 Designation:- Executive Engineer
 RWD, Regional Laboratory, Bhopal.

30.07.2021
 (Signature)