

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>AKAUNI TO POHE ROAD</u>		
Hazards	Flood/Rain / <u>5 yr Maintenance</u>	
Division: <u>JAMUI</u>	District: <u>JAMUI</u>	Actual Length (in km): <u>8.00 KM</u>
Damage Length (in km):	Damages Location/Chainage:	
Name of Scheme/Programme:	<u>3054 MR SHRENI-1</u> <u>4th yr. of Maintenance</u>	
Status of Project:	☒ Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC)	<u>S</u>
a)	Condition of Surfacing	<u>S</u>
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	<u>-</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>-</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	<u>-</u>
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Maintenance work of road done satisfactorily.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

30.07.21