

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 31-07-2023		District: Sitamashi
Division : Belbundi		Length (km): 0.200
Name of the Road: Chandabhai's Pathwan's House to Kathor Village to Kathor Path		
Scheme/Programme: GTSNY		
SL No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks: —		
2.	Cross Drainage	No culvert
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:- —		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- —		
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) Unsatisfactory (U)

Name of Officer: Rana Basu Kumar Singh
 Designature: Executive Engineer
RWD, Regional Laboratory, Bhubaneswar.

31-07-2023
 (Signature)