

INSPECTION REPORT FOR ROUTINE MAINTENANCE

INSPECTION REPORT FOR ROUTINE MAINTENANCE		
Date of Inspection : 31.07.2021		District: Sitamashi
Division : Belkand		Length (km): 0.225
Name of the Road: P.P. S. P. H. K. V. Chya Vidyalyaya, Gidson ke Samip se Paschim to Gidson		
Scheme/Programme: MMHSY (Gen)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- —		
2.	Cross Drainage	No culvert
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:- —		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- —		
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory (5)

Name of Officer:- Rana Bidan Kumar Singh
Designature:- Executive Engineer
RD, Regional Laboratory, Bhopal.

(Signature)