Date o	f Inspection: 1.8.21 District: Nawada	Vamada			
Divisio	on: Rajayli Length (km): 1.568	Length (km): 1.568			
Name	of the Road: LO22 LakhPat Bigha To Bolia (Tray)	<2 )			
		,			
Sl. No.	The second secon	Remarks (S/U)			
1.	Pavement				
a)	Condition of Surfacing	5			
b)	Riding Quality	5			
c)	Road Camber	5			
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes			
e)	Contraction Joints provided or not (CC Pavement)	-			
f)	Compaction of flank/slope & raincuts if any	\$			
	Flank (chowder) who needs dressing .	to slown uts			
2.	He [0+0 0.2 KM- PCC] - Satisfactory.  10.2+0 1.56 - B.T] - Satisfactory.  Flank (chowder) plus needs dressing.  Cross Drainage  Cross Drainage	to South Ut			
. 7 97 10	77.5	to slown ut			
2.	Cross Drainage				
2. a)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting	<i>S</i>			
a) b) c) d)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts				
a) b) c) d)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance	\$ - - - \$			
2. a) b) c) d) bserva	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  tion Remarks:-	\$ - - - \$			
2. a) b) c) d) Observa  3. a)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  tion Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m	<i>S</i> -			
2. a) b) c) d) Observa  3. a)	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Condition of Vent Clearance  tion Remarks:-  Road Furniture  Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	<i>S</i> -			

Overall Rating	•		
O TOTALI TAKING	•	Satisfactory (S)/ Unsatisfactory (U)	5

Name of Officer:- R. P. Saw

T.A. RWD

Designature:- Worse Circle Gwan Designature:-

(Signature) A.E.