

Date of Inspection : 1-8-21		District: Nawada	
Division : Rajauli		Length (km): 2.64 km	
Name of the Road: 1029 Hqna to Gayam (Track-9)			
Scheme/Programme: PMGSY (Maintenance)			
Sl. No.	Parameters to be checked		Remarks (S/U)
1. Pavement			
a)	Condition of Surfacing		S
b)	Riding Quality		S
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		ys
e)	Contraction Joints provided or not (CC Pavement)		-
f)	Compaction of flank/slope & raincuts if any		-
Observation Remarks:- width of B.T. surface is shortened due to gram, Earth embedded on B.T. surface and at few length, due to encroachment by villagers for their pet animals.			
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		-
c)	Condition of railings/slab/approach for Bridges		-
d)	Condition of Vent Clearance		S
Observation Remarks:-			
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained		S
Observation Remarks:-			
4. Compliance History			
a)	Status of ATR's & any others		-

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) S

Name of Officer:- R.P. Saw
 Designature:- T.A. RWD
 1/8/21
 (Signature)
 1-8-21