Date o		,
	of Inspection: 1.8.21 District: N	qwqd9
Divisi	on: Ralayli Length (km):	1.302
	of the Road: LO37 Govindpy Road T	o Bishun Pyr (Track 17
	ne/Programme: pMGsy (Maintenancy	
SI. No. Parameters to be checked		Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	
b)	Riding Quality	5
c)	Road Camber	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any ation Remarks:-	5
	Flank (shoulder) Earthwork cultis in progren. [0400.4 - drened o.4 to end - th	progress.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including	its painting S
b) Condition of Abutment & Wing walls, Slab in RCC culverts		
b)	Condition of Abutment & Wing walls, Slab in RCC culv	erts
b) c)	Condition of Abutment & Wing walls, Slab in RCC culv Condition of railings/slab/approach for Bridges	erts
c) d)	Condition of railings/slab/approach for Bridges Condition of Vent Clearance	erts –
c) d)	Condition of railings/slab/approach for Bridges	
c) d) servat	Condition of railings/slab/approach for Bridges Condition of Vent Clearance	
c) d) servat	Condition of railings/slab/approach for Bridges Condition of Vent Clearance tion Remarks:-	m & 200m
c) d) servat	Condition of railings/slab/approach for Bridges Condition of Vent Clearance tion Remarks:- Road Furniture Whether sign boards/informatory/cautionary Board/ k	m & 200m
c) d) servat	Condition of railings/slab/approach for Bridges Condition of Vent Clearance tion Remarks:- Road Furniture Whether sign boards/informatory/cautionary Board/ katones/Pavement road markings are provided and maintain	m & 200m

Overall	Rating
---------	--------

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:- R.P. Saw

Designature:- T.A., RWD, works Gircle Swan

118121

1.8.21

(Signature) Scanned With CamScannel