

Date of Inspection : 02.08.2021

District: Motihari

Division : Chakia

Length (km): 2.140

Name of the Road: 1051-1021 to Patbariya

Scheme/Programme:

PMGSY

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	—
Observation Remarks:- At many stretches surface condition is poor & pot holes found		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	U
Observation Remarks:- In case of H.P. culvert head wall found — — not painted & vent also not cleaned		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)


Unsatisfactory

Name of Officer:-

Pranab Kumar

Designature:-

EE, Reg. Lab. Saram


 02/08/2021 (Signature)

 Date
 2/8/21