

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 01.08.2021

Division : Chakda

District : Motihari

Name of the Road : Mehri State Bank & Kather Maya Chowk Tak Path

Length (km): 1.920

Scheme/Programme: MR

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	U
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	—
Observation Remarks:- At several stretches road condition is poor, B.T. surface exposed, Pot holes found at different location.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	—
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Unsatisfactory

Name of Officer: Pramod Kumar

Designature: EE, Reg. Lab, Sasaram

(Signature)