

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 29.07.2021

District: Motihari

Division : Chakia

Length (km): 1.250

Name of the Road: PMGSY Road Harnaraing to Naya Tola Harnaraing via Prathmik Vishalaya Harnaraing

Scheme/Programme: MMGSY (Gen)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	—

Observation Remarks:-

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S

Observation Remarks:- Head wall of HP culvert not properly painted

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U

Observation Remarks:- 200M Stones not found

4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory

Name of Officer: Prasad Kumar

Designature: E. Regional Lab. Sasaram

29.07.2021

(Signature)